



FIG. 1**Optics vs. Gauge for Example 1**

FIG. 2


Example 1



BEST AVAILABLE COPY

FIG. 3


Comparative Example 1



BEST AVAILABLE COPY

FIG. 4


Comparative Example 2



BEST AVAILABLE COPY


FIG. 5

Comparative Example 1



BEST AVAILABLE COPY

FIG. 6a



Example 1
Gauge Variation: < 5%

Comparative Example 2
Gauge Variation: ~ 10%

FIG. 7a
Good
Example 1






FIG. 7b
Poor
Comparative Example 2



BEST AVAILABLE COPY


FIG. 8

**Crystallization Onset Temperature vs
Crystallization Half Life Time at 200C/min**



- Example 2 ■ Example 3 ▲ Example 8 × Example 1a * Example 5


FIG. 9



BEST AVAILABLE COPY

FIG. 10

Crystallization Onset Temperature vs ($t_c - t_o$) at
200C/min



- Example 2 • Example 3 • Example 8 • Example 1a • Example 5

BEST AVAILABLE COPY